DISTRIBUTOR ADVANCE SPECIFICATIONS (BOSS 302)

Distributor	Set Test Stand to 0° at 1000 Distributor rpm and 0 inches of Mercury			Set Test Stand to 0° at 250 Distributor rpm and 0 inches of Mercury			Set Test Stand to 0° at 1000 Distributor rpm and 0 inches of Mercury		
	C9ZF-E	5 10 15 20 25	0·1 2 1/2·5 1/2 4 1/2·7 4 1/2·7 4 1/2·7	7°	350 500 750 1000 1500 2000	0-1/2 0-1/2 0-1 3/4 2 1/2-4 3/4 7 3/4-10 8 1/2-11	11° 2000 rpm	5 10 15 20	0·2 3·6 5·6 5·6

## Glazier/Nolan Mustang Barn