

C50F-12127-E

(289 High Performance)

CENTRIFUGAL ADVANCE: Set the test stand to 0° at 250 rpm and 0 inches of mercury.

Distributor (rpm)	Advance (Degrees)	Vacuum (Inches of Mercury)
650	2¼-3¾	0
750	4-5½	0
1000	6½-7½	0
1600	7½-8¾	0
2000	8¼-9¾	0

Maximum Advance Limit14°

Glazier/Nolan Mustang Barn